

TITLE: **HS15 (non-Plus version), HS750 (non-Plus version), SuperSprint, and Signer/Popletter Repair Status**

Category: Plotters/Console Based Systems – Service/Support

Gerber FastFact #: 5255

Supplied by: Technical Hardware Support

Last Modified: 2/10/03

Summary: Gerber can not guarantee that we can repair the system's FAS-1 or GTP-336 boards.

Underlined text indicates change from the previous document.

HS15 (NON-PLUS VERSION), HS750 (NON-PLUS VERSION), AND SUPERSPRINT REPAIR STATUS

Please be aware of the following regarding these plotters:

Gerber can not guarantee that we can repair the system's FAS-1 or GTP-336 boards.

There are no replacement FAS-1 and GTP-336 boards available.
The entire system must be sent in for repair, not just the board.

IF the board can be repaired, repair charges will include the labor to do this (and this can be expensive).

Further information on the average cost of repair is available from Gerber Scientific Products Technical Hardware Support.

Re: The Signer/Popletter – There are no replacement carriages available for this system.